

TOLERANCES FOR SHAFT ALIGNMENT

The rotation speed of the shafts will decide the demands on the alignment. The table on this side can be used as a guidance if no other tolerances is recommended by the manufacturer of the machines.

The tolerances is set to the maximum allowed deviation from accurate values, with no consideration to if that value should be zero or compensated for thermal growth.

	Excellent		Acceptable	
Offset				
<i>rpm</i>	<i>mils</i>	<i>mm</i>	<i>mils</i>	<i>mm</i>
0000-1000	3,0	0,07	5,0	0,13
1000-2000	2,0	0,05	4,0	0,10
2000-3000	1,5	0,03	3,0	0,07
3000-4000	1,0	0,02	2,0	0,04
4000-5000	0,5	0,01	1,5	0,03
5000-6000	<0,5	<0,01	<1,5	<0,03
Angular error				
<i>rpm</i>	<i>mils/°</i>	<i>mm/100</i>	<i>mils/°</i>	<i>mm/100</i>
0000-1000	0,6	0,06	1,0	0,10
1000-2000	0,5	0,05	0,8	0,08
2000-3000	0,4	0,04	0,7	0,07
3000-4000	0,3	0,03	0,6	0,06
4000-5000	0,2	0,02	0,5	0,05
5000-6000	0,1	0,01	0,4	0,04

CONVERTING TABLES

Converting tables for the converting of measurement values from one unit to another.

Mass

gram (g)	ounce (oz)	pound (lb)
1	0,035	
28,35	1	
453,59	16	1
1000		2,205

Length


mil	mm	Inch	Foot	meter
0,0394	0,001			
0,05	0,00127			
0,3937	0,01			
0,5	0,0127			
1	0,0254	0,001		
3,937	0,1	0,0039		
5	0,127	0,005		
39,37	1	0,0394		
100	2,54	0,1		
1000	25,4	1	0,0833	
	304,8	12	1	0,3048
	1000	39,37	3,28	1

Temperature

°C	°F
-40	-40
-30	-22
-20	-4
-17,8	0
-10	14
0	32
10	50
20	68
30	86
37,8	100
40	104
50	122
60	140
70	158

Angle

arc sec.	mil/foot	mil/inch	mm/m	degree	inch/foot
1	0,06	0,005	0,005		
16,6	1	0,083	0,083		
	12	1	1	0,057°	0,012
	210	17,45	17,45	1°	0,21
	1000	83,3	83,3	4,75°	1



1. What is an acceptable tolerance for a motor and a pump rotating at a speed of 2900 rpm?